

Saco River Basin Water Quality Monitoring Program - 2008 Testing Season
Sampling Site Code OS9 - Cornish Station Bridge along Routes 5 and 117 in Cornish, ME

	<u>04/16/08</u>	<u>04/30/08</u>	<u>05/14/08</u>	<u>05/28/08</u>	<u>06/11/08</u>	<u>06/25/08</u>	<u>07/09/08</u>	<u>07/23/08</u>	<u>08/06/08</u>	<u>08/20/08</u>	<u>09/03/08</u>	<u>09/17/08</u>	<u>10/01/08</u>	<u>10/15/08</u>	<u>Average</u>
pH (units)			6.63	7.03	6.79	6.86			6.85	6.77	6.76				6.81
Temperature (°C)			14.65	17.10	22.80	25.30			22.80	21.10	19.70				20.49
Turbidity (NTU)			1.71	1.34	1.32	2.89			1.70	2.14	1.47				1.80
Dissolved Oxygen (mg/L)			12.94	10.56	7.36	8.87			24.40	8.81	8.87				11.69
Dissolved Oxygen (% saturation)			127.40	109.20	85.30	107.20			281.60	98.90	96.85				129.49
Total Kjeldahl Nitrogen (mg/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Total Phosphorus (ug/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Escherichia coli (colonies/100mL)	n/a	n/a	n/a	n/a	n/a	n/a	41.00	n/a	n/a	n/a	18.10	n/a	n/a	n/a	n/a

NOTES: