

**Saco River Basin Water Quality Monitoring Program - 2006 Season**  
**Sampling Site Code CC1 - Davis Park, below confluence of Saco River and Swift River, Conway, NH**

	<u>04/10/06</u>	<u>04/24/06</u>	<u>05/08/06</u>	<u>05/22/06</u>	<u>06/05/06</u>	<u>06/19/06</u>	<u>07/03/06</u>	<u>07/17/06</u>	<u>07/31/06</u>	<u>08/14/06</u>	<u>08/28/06</u>	<u>09/11/06</u>	<u>09/25/06</u>	<u>Average</u>	
pH (units)	8.24	8.93		7.27	8.15	6.90		8.60	6.80	7.06	7.05	9.16		7.82	
Temperature (°C)	6.30	7.45		8.70	230.00	19.30		21.00	19.70	17.40	15.60	15.10	14.70	34.11	
Turbidity (NTU)	0.54	0.70		1.57	0.72	0.63		0.60	0.51	0.75	0.50	0.44	0.54	0.68	
Dissolved Oxygen (mg/L)	12.96	13.04		9.42	10.09	8.23		8.39	8.11	8.76	9.79	8.95	9.73	9.77	
Dissolved Oxygen (% saturation)	104.80	108.35		80.70	94.60	89.30		94.60	88.50	91.20	97.90	88.80	95.85	94.05	
Total Kjeldahl Nitrogen (mg/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Total Phosphorus (ug/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Escherichia coli (colonies/100mL)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a

NOTES: