

Saco River Basin Water Quality Monitoring Program - 2009 Season
Sampling Site Code CC1 - Davis Park, below confluence of Saco River and Swift River, Conway, NH

	<u>05/18/09</u>	<u>06/01/09</u>	<u>06/15/09</u>	<u>06/29/09</u>	<u>07/13/09</u>	<u>07/27/09</u>	<u>08/10/09</u>	<u>08/24/09</u>	<u>09/07/09</u>	<u>09/21/09</u>						<u>Average</u>	
pH (units)		7.04	6.71	6.45	7.15	6.85	6.49		6.91	7.80							6.93
Temperature (°C)	8.50	10.90	13.90	15.05	14.70	17.00	16.70		13.80	11.50							13.56
Turbidity (NTU)	0.91	0.34	0.85	3.90	0.69	0.73	0.40		0.45	0.46							0.97
Dissolved Oxygen (mg/L)	12.10	10.39	9.95	9.50	9.62	9.29	8.32		9.41	12.14							10.08
Dissolved Oxygen (% saturation)	102.90	93.90	96.20	94.40	94.80	95.90	85.30		90.90	111.40							96.19
Total Kjeldahl Nitrogen (mg/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Total Phosphorus (ug/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Escherichia coli (colonies/100mL)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a

NOTES: