

Saco River Basin Water Quality Monitoring Program - 2013 Season
Sampling Site Code CC1 - Davis Park, below confluence of Saco River and Swift River, Conway, NH

	<u>05/13/13</u>	<u>05/27/13</u>	<u>06/10/13</u>	<u>06/24/13</u>	<u>07/08/13</u>	<u>07/22/13</u>	<u>08/06/13</u>	<u>08/19/13</u>	<u>09/02/13</u>	<u>09/16/13</u>	<u>Average</u>
pH (units)	6.60	7.17	7.16	7.19	6.69	7.09	7.18	6.18	7.02		6.92
Temperature (°C)	8.50	10.10	15.10	18.10	19.20	19.70	16.20	16.70	18.10		15.74
Turbidity (NTU)	1.97	0.71	0.51	4.30	1.60	0.75	0.45	0.54	2.59		1.49
Conductivity	13.80	17.45	21.15	19.99	24.50	27.20	30.70	29.40	16.24		22.27
Dissolved Oxygen (mg/L)	11.08	10.95	9.52	8.88	8.50	8.26	9.09	9.18	8.85		9.37
Dissolved Oxygen (% saturation)	96.05	97.10	96.00	95.65	93.10	91.30	93.30	95.40	95.70		94.84
Total Kjeldahl Nitrogen (mg/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a		n/a
Total Phosphorus (ug/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a		n/a
Escherichia coli (colonies/100mL)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a		n/a

NOTES: