

Saco River Basin Water Quality Monitoring Program - 2016 Season

Sampling Site Code CC1 - Davis Park, below confluence of Saco River and Swift River, Conway, NH

	<u>05/16/16</u>	<u>05/30/16</u>	<u>06/13/16</u>	<u>06/27/16</u>	<u>07/11/16</u>	<u>07/25/16</u>	<u>08/08/16</u>	<u>08/22/16</u>	<u>09/05/16</u>	<u>09/19/16</u>					<u>Average</u>	
pH (units)	6.30	n/a	6.39													6.34
Temperature (°C)	10.10	n/a	13.55													11.83
Turbidity (NTU)	0.91	n/a	1.00													0.95
Conductivity	17.04	n/a	27.30													22.17
Dissolved Oxygen (mg/L)	10.32	n/a	9.34													9.83
Dissolved Oxygen (% saturation)	94.25	n/a	92.05													93.15
Total Kjeldahl Nitrogen (mg/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Total Phosphorus (ug/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Escherichia coli (colonies/100mL)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a

*

NOTES: