

Saco River Basin Water Quality Monitoring Program - 2016 Season
Sampling Site Code CC1 - Davis Park, below confluence of Saco River and Swift River, Conway, NH

	<u>05/16/16</u>	<u>05/30/16</u>	<u>06/13/16</u>	<u>06/27/16</u>	<u>07/11/16</u>	<u>07/25/16</u>	<u>08/08/16</u>	<u>08/22/16</u>	<u>09/05/16</u>	<u>09/19/16</u>		<u>Average</u>	
pH (units)	6.30	n/a	6.39	6.62	6.56	6.58						6.49	
Temperature (°C)	10.10	n/a	13.55	19.95	17.15	20.75						16.30	
Turbidity (NTU)	0.91	n/a	1.00	0.58	1.23	0.69						0.88	
Conductivity	17.04	n/a	27.30	37.60	20.66	28.90						26.30	
Dissolved Oxygen (mg/L)	10.32	n/a	9.34	8.37	9.22	8.33						9.11	
Dissolved Oxygen (% saturation)	94.25	n/a	92.05	93.40	96.65	94.40						94.15	
Total Kjeldahl Nitrogen (mg/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Total Phosphorus (ug/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Escherichia coli (colonies/100mL)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a

*

NOTES: