

Saco River Basin Water Quality Monitoring Program - 2016 Testing Season
Sampling Site Code MPB22 - Below Moose Pond off Route 160 in Denmark, ME

	<u>05/17/16</u>	<u>05/31/16</u>	<u>06/14/16</u>	<u>06/28/16</u>	<u>07/12/16</u>	<u>07/26/16</u>	<u>08/09/16</u>	<u>08/23/16</u>	<u>09/06/16</u>	<u>09/20/16</u>	<u>Average</u>
pH (units)	6.28	6.65	6.68	6.81	6.73	6.76	6.69				6.65
Temperature (°C)	12.90	21.25	17.75	23.95	22.50	25.95	23.90				21.17
Turbidity (NTU)	0.76	0.75	0.96	0.68	0.67	0.85	0.64				0.76
Conductivity	25.15	24.50	24.95	25.65	25.85	25.65	25.70				25.35
Dissolved Oxygen (mg/L)	10.32	8.62	9.08	7.78	8.22	7.57	7.97				8.51
Dissolved Oxygen (% saturation)	98.70	98.75	97.10	93.35	95.65	94.95	94.70				96.17
Total Kjeldahl Nitrogen (mg/L)											
Total Phosphorus (mg/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Escherichia coli (colonies/100mL)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a

NOTES:

*