

**Saco River Basin Water Quality Monitoring Program - 2008 Testin  
 Sampling Site Code S10 - off Route 11 in Standish, ME**

	<u>04/16/08</u>	<u>04/30/08</u>	<u>05/14/08</u>	<u>05/28/08</u>	<u>06/11/08</u>	<u>06/25/08</u>	<u>07/09/08</u>	<u>07/23/08</u>	<u>08/06/08</u>	<u>08/20/08</u>	<u>09/03/08</u>	<u>09/17/08</u>	<u>10/01/08</u>	<u>10/15/08</u>	<u>Average</u>
pH (units)	-		6.64	7.04	6.82	6.74	7.01	6.87	6.59	6.90	6.99	7.13	6.75	6.80	6.86
Temperature (°C)	-		13.00	16.30	22.50	21.80	25.60	22.70	20.40	19.80	19.90	18.00	16.40	13.40	19.15
Turbidity (NTU)	-		1.82	1.44	1.70	2.23	1.35	1.61	2.48	3.22	1.60	1.58	1.93	1.11	1.84
Dissolved Oxygen (mg/L)	-			7.70	7.53	8.04	7.92	8.41	8.52	8.86	8.84	5.16	9.13	9.61	8.16
Dissolved Oxygen (% saturation)	-			78.80	87.00	88.80	96.80	97.50	94.40	97.00	96.30	54.50	92.90	92.30	88.75
Total Kjeldahl Nitrogen (mg/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Total Phosphorus (ug/L)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a
Escherichia coli (colonies/100mL)	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a	n/a

NOTES: