

Saco River Basin Water Quality Monitoring Program - Year 2001
 Testing Results for Sampling Site Code S19
 Skelton Head Pond off Union Falls Road in Dayton, ME

	04/13/01	04/27/01	05/11/01	05/25/01	06/08/01
pH (units)		6.72			
Temperature (°C)		19.55			
Turbidity (NTU)		1.39			
Dissolved Oxygen (mg/L)					
Dissolved Oxygen (% saturation)		86.30			
Total Kjeldahl Nitrogen (mg/L)					
Total Phosphorus (mg/L)					
Escherichia coli (colonies/100mL)		62.83			
	06/22/01	07/06/01	07/20/01	08/03/01	08/17/01
pH (units)					7.06
Temperature (°C)					25.30
Turbidity (NTU)					1.40
Dissolved Oxygen (mg/L)					9.05
Dissolved Oxygen (% saturation)					109.40
Total Kjeldahl Nitrogen (mg/L)					
Total Phosphorus (mg/L)					
Escherichia coli (colonies/100mL)					93.00
	08/31/01	09/14/01	09/28/01	10/12/01	10/26/01
pH (units)	6.73	6.79	6.61	6.47	6.64
Temperature (°C)	23.40	21.80	19.50	15.30	12.00
Turbidity (NTU)	1.57	2.10	1.26	1.06	0.93
Dissolved Oxygen (mg/L)	6.47	7.63	7.03	8.17	8.93
Dissolved Oxygen (% saturation)	76.70	88.00	77.20	82.60	83.90
Total Kjeldahl Nitrogen (mg/L)					
Total Phosphorus (mg/L)					
Escherichia coli (colonies/100mL)	69.00	19.00	93.00	69.00	34.00