

**Saco River Basin Water Quality Monitoring Program - 2016 Testing Season**  
**Sampling Site Code S19 (S19U) - Skelton Head Pond off Union Falls Road in Dayton, ME**

	<u>05/20/16</u>	<u>06/03/16</u>	<u>06/17/16</u>	<u>06/24/16</u>	<u>07/08/16</u>	<u>07/22/16</u>	<u>08/05/16</u>	<u>08/19/16</u>	<u>09/02/16</u>	<u>09/16/16</u>	<u>Average</u>
pH (units)	6.54	6.62	6.48								6.55
Temperature (°C)	15.20	20.90	20.30								18.80
Turbidity (NTU)	1.73	1.19	3.18								2.03
Conductivity	22.60	27.15	25.20								24.98
Dissolved Oxygen (mg/L)	8.77	8.45	8.16								8.31
Dissolved Oxygen (% saturation)	86.95	95.10	91.00								93.05
Total Kjeldahl Nitrogen (mg/L)	0.47										0.47
Total Phosphorus (ug/L)	20.000										20.00
Escherichia coli (colonies/100mL)	1.00	6.30	9.80								5.70

NOTES: