

**Saco River Basin Water Quality Monitoring Program - 2014 Testing Season**  
**Sampling Site Code S31 - Saco River off Rotary Park in Biddeford**

		<u>06/11/14</u>	<u>06/18/14</u>	<u>06/25/14</u>	<u>07/02/14</u>	<u>07/10/14</u>	<u>07/16/14</u>	<u>07/23/14</u>	<u>07/30/14</u>	<u>08/06/14</u>	<u>08/13/14</u>	<u>08/20/14</u>	<u>08/27/14</u>	<u>9/3/2014</u>	<u>Average</u>
pH (units)															#DIV/0!
Temperature (°C)															#DIV/0!
Turbidity (NTU)															#DIV/0!
Conductivity															#DIV/0!
Dissolved Oxygen (mg/L)															#DIV/0!
Dissolved Oxygen (% saturation)															#DIV/0!
Total Kjeldahl Nitrogen (mg/L)															
Total Phosphorus (ug/L)															
Escherichia coli (colonies/100mL)	1	61.30	34.50	23.10	88.40	66.30		41.40	980.40	31.80	47.10	83.30	248.90		155.14
	2	48.8	37.9	6.3	58.3	25.9		35	866.4	21.6	38.9	60.5	172.5		
	3	101.2	41.4	9.7	65.7	36.4		41.7	980.4	15.6	21.6	82	146.7		